## HISTORIC AMERICAN BUILDINGS SURVEY

## INDEX TO PHOTOGRAPHS

Franklin School Southeast corner 13th and K Streets, NW Washington District of Columbia HABS No. DC-289

## Ronald Comedy, Photographer May, 1969

and the second s	
DC-289-1	WEST (13TH STREET) FRONT
DC-289-2	NORTH (K STREET) SIDE
DC-289-3	WEST FRONT AND NORTH SIDE
DC-289-4	DETAIL, WEST FRONT, DOORWAY AND WINDOWS
DC-289-5	DETAIL, NORTH SIDE, IRON RAILING
DC-289-6	DETAIL, CORNER TOWER
DC-289-7	DETAIL, WEST FRONT, ROOF AND CORNICE
DC-289-8	DETAIL, WEST FRONT, ROOF SHINGLES AND DECORATION
DC-289-9	DETAIL, ROOF CRESTING
DC-289-10	INTERIOR, FIRST FLOOR, STAIRWAY
DC-289-11	INTERIOR, FIRST FLOOR, STAIRWAY, NEWEL POST
DC-289-12	INTERIOR, SECOND FLOOR, HALLWAY
DC-289-13	INTERIOR, SECOND FLOOR, DETAIL OF TIN CEILING
DC-289-14	INTERIOR, THIRD FLOOR, HALLWAY
DC-289-15	INTERIOR, THIRD FLOOR, CLASSROOM
DC-289-16	INTERIOR, THIRD FLOOR, STAIR DETAIL
DC-289-17	INTERIOR, THIRD FLOOR, DETAIL OF COLUMN
DC~289-18	INTERIOR, LOWER ATTIC
DC-289-19	INTERIOR, LOWER ATTIC, DETAIL OF TROMPE D'OEIL PAINTED ARCHES
DC-289-20	INTERIOR, LOWER ATTIC, DETAIL OF GAS JET IN CORRIDOR
DC-289-21	INTERIOR, UPPER ATTIC, CATWALK
DC-289-22	INTERIOR, UPPER ATTIC, DETAIL OF FRAMING
the state of the s	